Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 8/4/2015, 8/5/2015, 8/6/2015 Man Days:	
Inspection Unit: Tuscola	
Location of Audit: Tuscola	
Exit Meeting Contact: Kevin Glaspy	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Donald Hankins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#: (800) 755-5000	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Kevin Glaspy	Quality Assurance	

	CUSTOMER METER & REGULATOR	Status
Category Comment:		
Customer meters and re	gulators were not inspected during this audit	
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Not Checked
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Not Checked
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Not Checked
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Checked
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Not Checked
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Not Checked
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Not Checked
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Checked
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Checked
	CATHODIC PROTECTION	Status
Category Comment:		
Cathodic readings were not ins	spected at the time of this audit.	
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Not Checked
[192.465(a)]	Were pipe to soil readings taken?	Not Checked
[192.465(b)]	Were rectifier installations inspected?	Not Checked
[192.465(a)]	Were isolated mains/services tested?	Not Checked
[192.465(c)]	Were critical/non critical bonds tested?	Not Checked
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Not Checked
[192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
[192.479(a)]	Is the above ground piping coated or painted as required?	Not Checked
[192.479(c)]	Is the pipeline free of corrosion or pitting?	Not Checked
	DAMAGE PREVENTION	Status
Category Comment:		
Notification of planned excavat	tion activities were not inspected during this audit.	
[192.614]	Does the operator have a valid notification of planned excavation activities?	Not Checked
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Checked
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Checked
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory

AMEREN ILLINOIS COMPANY/8-6-2015

Page 2 of 6

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
Line markers were inspe	cted at two regulator stations that are listed below.	
Station number XT - 12 Station number XT - 23		
[192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
General Comment:		
Line markers are being r	maintained over buried mains in the area of the regulator stations.	
[192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Satisfactory
General Comment:		
Line markers are being r	maintained over buried mains in the area of the regulator stations.	
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
General Comment:	<u> </u>	
Line markers had proper	marking on each line marker at the regulator station.	
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
General Comment:		
The line markers had the	e emergency numbers on them with the number being 1-800-755-5000.	
PRESSI	URE LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Satisfactory
General Comment:		
Equipment at the regulat	for stations have been inspected within the last 15 months.	
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory

AMEREN ILLINOIS COMPANY/8-6-2015

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

General Comment:		
Station numbers XT-12 and st	ation number XT-23 have a fence around the regulator station.	
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Satisfactory
General Comment:	1	
Gauges were inspected during	this audit.	
[192.743(a)]	Is overpressure protection provided on the pipeline downstream of the take point?	Not Checked
General Comment:		
Overpressure protection was r	not inspected at the time of this audit.	
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
General Comment:	·	
Supports were being protected	my noncombustible materials.	
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Satisfactory
General Comment:		
Pressure relief piping had veni	t caps placed on them.	
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Satisfactory
General Comment:	,	
Valves were locked in the open	n position by using pins through the shutoff valves.	
	VALVE MAINTENANCE	Status
Category Comment:	·	
Valves were not inspected dur	ing this audit.	
[192.747(a)]	Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Not Checked
	ODORIZATION OF GAS	Status
Category Comment:		
Odorization was not inspected	during this audit.	
[192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Checked
[192.625(f)]	Was the operator's equipment calibrated as required?	Not Checked
	TRANSMISSION	Status
Category Comment:		
Transmission valves were	e not inspected at the time of this audit.	
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Not Checked
[192.745(a)]	Were the valves inspected accessible?	Not Checked
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Checked
[192.179(c)]	If blow down activities were observed, were the blow down valves properly sized to allow the transmission pipeline to vent as rapidly as practicable and did the blow down vent freely to atmosphere away from any hazards?	Not Checked
	MARKING OF MATERIAL	Status
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Satisfactory
General Comment:	·	
Staff inspected pipe and	fittings and they were properly marked.	
	OPERATOR QUALIFICATION	Status
Category Comment:		
A Protocol 15 was not co	nducted at this audit.	
Was a PHMSA Forn	n 15 Operator Qualification Field Inspection Protocol Form completed?	No

AMEREN ILLINOIS COMPANY/8-6-2015 Page 5 of 6

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

AMEREN ILLINOIS COMPANY/8-6-2015 Page 6 of 6